

## ABSTRACT

A method for marking a polymeric surface includes directing a first laser beam on the surface to form a lightened area on the surface and directing a second laser beam upon the lightened area to form a mark darker than the lightened area.